

ENGINEERING CHANGE NOTICE

DART AEROSPACE LTD				ECN #:
Date: 05-06-30				706
Project No: D412-705	Created By: <u>TH</u>	Checked By: <u>TH</u>		
Project Name: DRIVE SHAFT ACCESS PANEL	Approved By: <u>TH</u> (Proj. Manager)	Approved By: <u>TH</u> (Management if reqd)		N/A

Description of Change:

RELEASE DSI 9306 REV. A
D3256 REV. B

Notification/Acceptance	Affected	Initials	Authorization	
QA	✓	<u>KJ</u>		
Production	✓	<u>U</u>	<i>OK per TH</i>	
Planning	✓			
Marketing	✓	<u>SW</u>		
Engineering Actions	Yes	No	Responsible	To happen by:
Update Blue/Pink File	✓		KJ	05.07.05
Update DSI File	✓		KJ	05.07.05
Update D-Part Master Binder	✓		KJ	05.07.05
Update Grey Project Binder	✓		KJ	05.07.05
Update DEO Binder	✓		KJ	05.07.05
Update Master Document List	✓	✓		
Update Drawing Approval Record	✓		KJ	05.07.05
Update Change Record Form	✓		RF	05.07.05
Move Electronic File	✓		KJ	05.07.05
Notify TCA of Change	✓		DS	05.09.30
Notify FAA of Change	✓			
Update QSI 021	✓			
Update QSI 036	✓			
Scan Documents	✓		KJ	05.07.05
Update MIS Database	✓		KJ	05.07.05
Update Access Database	✓		KJ	05.07.05
Verification ARC	✓			
Create/Update STC Approval List	✓			
Create/Update IPP's	✓		Item RF/KJ	05.07.05
Create/Update BOM's	✓	✓		
Create/Update PPP's	✓		KJ	05.07.04
Update Paperwork Kits in Production	✓		KJ	05.07.05
Update Paperwork Kits in Stock	✓		RF/KJ	05.07.05
Rework/Scrap Current Production	✓		JM	ASAP
Rework/Scrap Kits in Stock?	✓		JM	ASAP
Create/Update Laminated Dwgs	✓			
Create/Update Controlled Dwgs	✓		KJ	05.07.05
Create/Update FAI sheets	✓			
Create/Update CNC Programs	✓			
Create/Update Tooling	✓			
Create/Update DXF File	✓			
MPP required?	✓			
Notify Previous Customers	✓			
Notify Eurocopter France	✓			

Notes:

- Jason Loader already take care the customer in Miami by supplied a copy of DSI 9306 Rev A to rework of D412-705-015 B21654. Also DART already sent a replacement D3256-041 Rev. B Access Panel.
- Update current production with the new Dwg of D3256-3 Rev. B gasket.
- Update IPP per D3256- Rev. B.
- Update PPP to add DSI 9306 Rev. A & D412-705-015 at C46002
- Rework current stock by removing existing D3256-3 Rev. A gasket and replacing with new gasket as per D3256 Rev B. Change label to D412-705-015 at C46002.